

## **Appendix A**

### **Marked Up Version of Abstract**

A screw element with a tool engagement means ~~(5, 6)~~ and a spring element ~~(8)~~ which is formed on the screw element in one piece in coaxial relationship with the screw axis ~~(7)~~ and which with its free edge defines a workpiece contact plane which is perpendicular to the screw axis and which is at an axial spacing from the screw element ~~(1)~~, is distinguished in that the spring element ~~(8)~~ is mounted at the periphery of the screw element, that is to say a screw head ~~(4)~~ or a screw nut, it projects radially beyond the periphery and it forms a workpiece contact means ~~(9)~~ which is disposed outside the periphery and which is in concentric relationship with the screw axis ~~(7)~~.

~~(Figure 1)~~